

## De Soto National Memorial (DESO)

**Table D22.** Summary of Findings for DESO.

Exposure level	# of assets	% of assets	CRV	% of total CRV
High Exposure	10	100%	\$3,366,160	100%
Limited Exposure	0	0	0	0
<b>TOTALS</b>	<b>10</b>	<b>100%</b>	<b>\$3,366,160</b>	<b>100%</b>

### **Park visit**

N/A

### **Park contacts**

N/A

### **Primary data utilized**

1) NPS FMSS location hierarchy report

### **Process/methods for exposure determination**

Discussions with NPS led to the conclusion that all SER parks (with a few exceptions) should have ALL assets listed as high exposure. This is due to the overall low elevation of the coastal parks in the region and the extreme vulnerability of these units to tropical storms.

### **DESO Documents**

High exposure assets\*

\*Assets sorted by values for:

- 1) Optimizer Band (low to high)
- 2) API (high to low)
- 3) FCI (low to high)

**Table D23.** DESO High Exposure Asset List.

ID	Asset Code	Location Code (Description)	CRV	Optimiz Band	API	FCI
1	7500	111652 (Interpretive Media Talking Chickee Hut)	\$30,129	0	n/a	0
2	7500	231801 (DESO- Visitor Center Interpretive Media)	\$96,101	0	n/a	0
3	7500	231813 (DESO- Nature Trail Interpretive Media)	\$81,578	0	n/a	0
4	4100	50396 (Visitor Center)	\$1,699,416	1	n/a	0.06
5	4100	75316 (Maintenance/Administration Building)	\$758,247	2	n/a	0.03
6	2100	50400 (DESO Nature Trail)	\$180,377	2	n/a	0.04
7	1300	53322 (Maintenance Shell Road/Parking RT 0901)	\$72,045	3	n/a	0
8	4100	75320 (Irrigation Pump House)	\$19,689	3	n/a	0
9	4100	75317 (Fuel and Paint Shed)	\$32,246	3	n/a	0.08
10	1300	50413 (Paved Road/Parking-RT 900)	396331.25	3.00	n/a	0.17